




Notice Sheet 1

Please leave in customer's vehicle

Important Notice

You may be aware of a possible noise when fitting an aftermarket clutch to the VDJ, HDJ & HZJ Landcruiser. This noise may be heard during gear changes or at idle with the clutch disengaged usually around 2000rpm and higher. This is not a failure of any part and is not causing any damage to the vehicle.

Thank you for choosing NPC





Notice Sheet 1

Please leave in customer's vehicle

Important Notice

You may be aware of a possible noise when fitting an aftermarket clutch to the VDJ, HDJ & HZJ Landcruiser. This noise may be heard during gear changes or at idle with the clutch disengaged usually around 2000rpm and higher. This is not a failure of any part and is not causing any damage to the vehicle.

Thank you for choosing NPC